



These articles and information is brought to you by The 1937 and 1938 Buicks Club. For more information please contact us at;

<http://autos.groups.yahoo.com/group/1937and1938Buicks/>

or

WWW.1937and1938Buicks.com

-- Warning Notice --

It the mission and goal of 1937 and 1938 Buicks Club is to provide information, helpful hints, advice, directions and reference information for the repair, maintenance, authentic restoration and knowledge development in regards to 1937 and 1938 Buick's. Content is offered as informational only.

The 1937 and 1938 Buicks Club does not knowingly accept false or misleading content or advertising. Nor does The 1937 and 1938 Buicks Club assume any responsibility for the consequences that may occur should any such material appear.

The 1937 and 1938 Buicks Club does not guarantee the quality of any information which is included in this or any other publication. Under no circumstances shall The 1937 and 1938 Buicks Club be liable for any damages, losses, or injuries resulting from use reliance on the content of this or any other publication. Any reliance on this or any other publication content is at your own risk.

As a precautionary measure, The 1937 and 1938 Buicks Club strongly recommends that you contact a professional mechanic or restoration shop to check your work or answer specific questions.

-- Copyright Notice --

All rights reserved. All documents and publications on The 1937 and 1938 Buicks Club web site or that can be downloaded from The 1937 and 1938 Buicks Club web site are protected under both U.S. Federal copyright law and international treaties. No component of this site, including text, images and computer code, may not be reproduced or copied in any form or by any means--electronic, graphic, digital or mechanical, including photocopying or information storage & retrieval systems--without the express prior written permission of The 1937 and 1938 Buicks Club.

TORQUE TUBE

THE NEWS PUBLICATION FOR MEMBERS OF THE 1937-1938 BUICK CLUB



VOLUMN XV • NUMBER 1 • SEPTEMBER / OCTOBER 1996

BUICK
1937 1938

TORQUE TUBE

THE NEWS PUBLICATION FOR MEMBERS OF THE 1937-1938 BUICK CLUB

VOLUME XV • NUMBER 1 • SEPTEMBER / OCTOBER 1996

THE 9th CYLINDER

BY HARRY LOGAN #651, Editor

This is the September/October *Torque Tube*, the first of six issues in our 1996-1997 publishing year. We ended our 1995-1996 year August 31 with a total of **514** paying members, the highest number in the Club's 16 year history!

Greg Marshall (#148) recently returned from a trip to Oregon and Washington where he spotted lots of old trucks and cars sitting on farms etc. But not '37 or '38 Buicks. He did see an early 60's Buick "Woody" rotting away in Northern California.

'37 and '38 Buicks had locking handles on the front passenger side door only. Many people prefer the locking handle to be on the left or driver's side. This can be done by reversing the front door handles. My car is like this and I lost one point in a show because of the switch.


But maybe I shouldn't have lost that point because page 1-23 of the 1938 Shop Manual has this paragraph:

Note: Left front doors on all series can be equipped with

locking handles. This is done by removing the production left front door handle and installing a production right front door handle. The cylinder lock should be ordered by key number so that the same key will fit both front doors. Thanks to Wayne Yonce (#1034) for pointing this out.

Photographed with a '38 Buick Special convertible sedan are Hollywood stars Jackie Coogan and his wife Betty Grable. They were married in 1937 and appeared together in the film "*College Swing*." Grable was born in St. Louis in 1916. Coogan was born in Los Angles in 1914. He co-starred with Charlie Chaplin in the film "*The Kid*." Coogan went on to become one of the most successful child stars in film history.

We recently featured a story by **John Baine** (#1019) in Canada about how "*You Can Only Drive One Car At A Time!*" John wrote to say that since the article appeared in the *Torque Tube*, he has rebuilt his 38-81 McLaughlin



FOUNDED IN 1980 BY DAVE LEWIS



Roadmaster's front end, brakes, carburetor and fuel pump. He also installed a new exhaust, cleaned and sealed the gas tank, installed new fuel lines, repaired one running board and installed new wiring. He has been driving it all summer. John says it runs great and doesn't overheat.

Cecil Don (#637) took this photo of **Jesse Cahue's** (#719) original 1938 jack at the **BCA Nationals** in Texas. All the original ones I've seen including this one

were green. One member described it as "Lawn Boy" green after the color of this brand of lawn mower.


This diagram from the 1938 Owners Manual shows how you raise and lower the jack. Personally, I wouldn't try this. The jack looks like an accident waiting to happen. I'd be afraid the jack would tip over in the stand and bring the car with it. Also, I know

one member who tried to use his original jack and the cast iron body broke apart.

Les Terry (#1138) in Michigan owns a very nice 1938 Special 4-Door Slant Back Sedan Model 47. Buick made over eleven thousand of this model.

Les recently acquired two more '38 Specials, a Business Coupe 38-46 and a Sport Coupe Model 46S with jump seats. Both require restoration. The Sport Coupe will be the easiest, as it is a nice original all-there car. The Business Coupe was a "barn car." It has an excellent rust-free body with a few missing parts. Hopefully, in a couple of years Les will blast off with two 1938 Specials!

Business Coupe was a "barn car." It has an excellent rust-free body with a few missing parts.



around the neighborhood in my '37 Century

TORQUE TUBE

The **TORQUE TUBE** is published bi-monthly for the enjoyment of the **1937-1938 Buick Club**. Membership dues are \$34.00 per year US, \$35.00 per year Canada and \$40.00 per year for all others. All issues mailed First Class and Overseas issues are mailed Air Mail-Printed Matter unless Surface Mail, at \$35.00 per year, is requested. All memberships run September 1 to August 31 of the following year. Persons joining during the year will receive all back issues from September 1. All payments must be in U.S. funds. Please make your check payable to the **1937-1938 Buick Club**.

Please send all articles, ads subscriptions and inquiries, etc. to:

THE TORQUE TUBE
1005 RILMA LANE
LOS ALTOS, CA 94022 USA

YOU CAN REACH HARRY LOGAN by
PHONE/FAX (415) 941-4587

or by E-mail: harrylogan@earthlink.net

Editor.....Harry Logan, #651
Art Director.....Dug Waggoner, #10

Printer Liaison.....Bill Olson, #427
Printer.....Conrads Printing, Lancaster, Ohio

All rights reserved. No part of this newsletter may be reproduced in any form without written permission from THE TORQUE TUBE.

Coupe. José is looking to buy a '37 Coupe to go with his '37 Century and Roadmaster Sedans.

The last issue of the **Torque Tube** featured José and his '37 Buicks and airplane. He had just returned from the Antique Airplane Fly-In in Oshkosh, WI. He said flying over the Golden Gate Bridge and the San Francisco Bay Area was quite an experience and a very beautiful sight.

José bought an airplane book at the Air Show. One of the photos shows a sidemounted beige colored 1938 Phaeton near a plane.

It has blackwall tires, a non-original rear window and the bottom of the door and the running board show some damage. It also shows the correct way to paint phaeton removable center posts. There should be body color on the two outer edges of the post with a chrome center strip.

José left me a Spanish language magazine from Columbia. This white 1938 Buick Special 4-Door Trunk Back Sedan with red wheels was featured in an ad for a Limousine Service in Bogota, Columbia.

Graeme Letica

(#769) faxed me from New Zealand warning that poor quality antique car **suspension parts** are coming into the US from India. Graeme says a friend in the US told him about this situation and that some big US suppliers are purchasing quantities of this junk and passing it on to unsuspecting car owners.

Graeme says he has had a similar experience in New Zealand when someone tried to sell him poor quality imported parts for MAN and Mercedes-Benz busses.

We were sorry to learn of the death of **Leo McNamara** (#990) in August. Leo lived in

Elmhurst, Illinois and owned a 1937 Special 4-Door Slant Back Sedan Model 47.

Make sure your wheel bolts are tight. One of our members watched in horror through his rear view mirror as his left rear wheel came off and started bouncing down the road. The car came

to an abrupt stop dragging on the backing plate. His fender also was damaged. All this due to the wheel bolts coming loose. It's a good idea before leaving for a ride to go

around to each tire, grasp the tire, at the top with both hands, and give it a mighty shake. If you feel any loose movement in the tire, pop the hub cap and check the bolts and your front spindle nuts.


Yes! You can still find rare Buick parts in your local junk yard. **Ed Bohn** (#199) in the San Francisco Bay Area told me he found a '37/38 Side-

mount side plate (missing the BUICK badge) and tread cover with attached back plate for a very reasonable price. Unfortunately it was for the left side and not a pair.

Al Mc Michael (#319) replaced the original interior of his '38 Century Sedan with a new one from Hampton Coach. In doing so, he found a screwdriver with a wooden handle painted red behind the left rear armrest. It's 8 1/4" (21 cm) long with a metal collar stamped "Made in the USA". Could it be from a factory worker in 1938?

Under the front seat Al found a 1953 Pennsylvania inspection sticker and the clock tag for the glove box clock. Under the rear seat he found hair pins and a Phillies cigar wrapper. Al suggests we start a new column entitled "What I Found In My Buick."

This is what **Lauren Matley** (#46) repro



Buick sidemount emblems look like. **Peter Breitenstein** (#989) in Namibia, Africa ordered a pair and says they are SUPER!! Peter says his '38 Century Sedan looks complete for the first time in the 24 years that he has owned it.

Peter says he bought a steering lock for his '38 Limited from **Jimmy Haggland** (#299) in Cape Town, but it did not have a key. So

Peter took it to a local locksmith. He had a box of old keys and the first one he pulled out fit the lock perfectly. What luck!

My mailbox has been flooded with several hundred renewals. Glad to see them come in. Along with the renewal checks were some nice words. **Will Siegfried** (#1117) says "Thanks for providing such a valuable and enjoyable publication. I always get a real zing when I find a new edition in my mailbox."

Erv Hutjens (#1067) also writes "Keep up the great job on the Torque Tube. It's the only magazine I read three times." Thanks for the kind words.

Von Hardesty (#964) suggested members write in with the reasons why they prefer 1937 or 1938 Buicks. This information would be used

for a two part article, "Why I Prefer the 1937 Buick" and "Why I Prefer the 1938 Buick." So please let me know which year **you** prefer and why. Thanks.


If you want to rerun a *Parts For Sale* ad, just cross out the items you sold and mail or FAX the revised list to me. I'll take care of the rest.

A question was asked about rear folding bumper guards. To

my knowledge, Buick did not have an accessory folding rear bumper guard in 1937. But they did in '38, '39 and '40 and maybe other years as well. The bottom left photo shows a '38 folding guard on the left and a '39/40 model on the right.

David Pitzer (#971) in Peoria, IL sent in this old newspaper clipping (bottom right photo). The photos show a bullet-riddled and bloody 1937 Buick trunk back sedan in which gangster Phillip Stumpf was murdered in 1946. Stumpf's hat with a hole in the crown, lies on the front seat. Nine bullets were fired through the rear of the car, with five going through the front windshield.

I received two good tips on the same subject recently, one from **John Johnson** (#697) and the other from **Bob Wilson** (#932) in Canada who reports he has had good results getting his 1937



cloisonné horn button and center grille emblem restored by a company called **Emblemagic**. The restorer's name is **Raymond Geschke, 8367 Shepard Rd., Macedonia, Ohio 44056. Phone (216) 467-8755**. He has the emblems re-chromed after he restores the cloisonné. Bob says it takes about 3 weeks and he's pleased with how his turned out.


After attending the Club's **East Coast Meet** in Pennsylvania (see story starting on page 6), my wife Margo and I spent a week in Washington, DC **Charles Jekofsky** (#534) took us in his 1974 Buick on three day trips to see the Gettysburg Civil War battlefield, Mt. Vernon, George Washington's home and Montecello, the home of Thomas Jefferson.

We also stopped to look at this '38 Century Sedan Model 61 in a gas station near Washington where I snapped the photo below of Charles. The car is in need of a complete restoration. Notice the front bumper does not have a hole for the BUICK 8 medallion. Nearly every 1938 Century I've seen has the medallion but this one doesn't. Another Buick mystery.

HELP! Does any member speak Finnish or know someone who does. I have several pages of Finnish text related to 1937 and 1938 Buicks used by Marshal Mannerheim and the Finnish Army in their battle to save Finland from the Soviet invasion of 1940. I'm sure the information and photos will be of interest to most Club members.

John Koutre (#593) writes: "A big thank you for the convertible door alignment article by David Bylsma on page 15 of the last issue. I was just a couple of days away from springing the driver's side door on my '39 Century convertible. I'm getting the car back together and the bottom trailing edge of the door was not flush with the body. David's advice worked great."

Some members have been planning next year's **East and West Coast Meets**. It looks like the **East Coast Meet** will be in Michigan and the **West Coast Meet** in Oregon. My wife and I had such a good time at the **1996 East Coast Meet** that we hope to make both next year. I'll keep you posted as plans develop.



COVER CARS

The front cover shows **Andy Diem** (#852) and his unrestored "Coronary" (dark) green 1937 Special Convertible Sedan Model 40C. This photo was taken at the Buick Meet in Tyson's Corner, Virginia (near Washington, DC) in early September. Until recently the car had its original cloth top. But Andy got caught in a rainstorm that ruined the fragile old top and it had to be replaced.

The car was purchased new in late 1937 by Mrs. Frances Sloane, widow of Mr. William Sloane, president of W & J Sloane Furniture Company. The car lived all of its life at the family country home in Mount Kisco, New York. Mrs. Sloane drove it summers only, until 1953 when she stopped driving. It was put in the garage with only 17,582 miles (28,131 km) on the odometer and prepared for long term storage.

Andy's mother-in-law, Mrs. Margaret Sloane Patterson, inherited the family country home along with the Buick in the early 1960's when her mother, Mrs. Sloane died.

The car remained in tomb-like storage until the summer of 1990, when it was removed. The back cover shows what the car looked like when it came out from its long sleep.

"Down by the Riverside" 1937-1938 BUICK EAST COAST MEET

By Harry Logan (#651)

The East Coast Meet was held at the 111 year old Riverside Inn in Cambridge Springs, Pennsylvania. My wife Margo and I arrived several days early, so we checked out the Inn and the small town of Cambridge Springs. It seems like a quiet town with a slow pace of life.

The photo of me below shows the large beautiful grounds and the porch surrounding the Inn. I particularly enjoyed the restaurant, antique furniture, paintings, and the wide porch. It was very peaceful sitting there in a rocking chair looking out at the beautifully landscaped grass and flowers with a creek in the distance. It was like being transported back to a more peaceful time.

We were blessed with entertainment on several



evenings with a songfest in the lounge. At the top of page 7 we see former editor **Bill Olson** (#427), **Jim Pascoe** (#881), **Clarence Hoffman** (#546) and **Steve King** (#776) singing to the accompaniment of **Al Pavlik Jr.** (#62) on the piano.

The Meet brought out about 20 cars including a 1936 Century 3-window coupe, a 1953 Super 2-Door Sedan and a new member, **Bill Tecco** (#1218), in a yellow 1937 Century Convertible. On Friday August 22, we made a 90 mile (144 km) round trip tour to Franklin, PA., named after Benjamin Franklin. Along the way we passed an Amish farm with several young girls wearing bonnets and long dresses watching as the old cars passed by. In Franklin, we



ate lunch in the Old Railroad Depot, (middle photo page 7) now a restaurant and lounge. Afterwards, some members visited the local antique stores.

The bottom photo shows **Jim Pascoe's** big, blue and impressive '38 Limited with a custom French body in the Depot's parking lot. Jim and his wife let us ride with them on the tour to Franklin. What luxury!

Shortly after this photo was taken a thunder-storm hit. Lightening and pelting rain was all around us as we waited under cover in the Depot for the storm to pass over us.

On a beautiful Saturday morning (August 23), we all left for member **Clarence Hoffman's** farm. Here the cars are lined up in the parking lot of Lake Pymatuning (top of page 8) while we watched thousands of fish, called Carp, come right up to the shoreline to get bread tossed to them. Several times we saw a raccoon dart out of his hole on the lake bank, grab a piece of bread and quickly return. Raccoon and Carp all trying to get a scrap of bread, it was quite a sight!

In the next photo (middle of page 8) Clarence (with hat) gave us directions as we prepared to leave



Lake Pymatuning and drive to his farm.

We had one more stop to organize the group where Clarence stepped out of his car wearing an interesting hat that reminded me of Teddy Roosevelt and the Rough Riders.

Finally we arrived at Clarence's farm (bottom of page 8). There are some parts of his farmhouse that date from the time of the Civil War (1860's). That's Clarence's black 38-40C in the foreground. He has several other Buicks including a brown 1937-46C Convertible and a 1938 Business Coupe which is parked outside with a mannequin behind the steering wheel! It scared some of us the first time we looked through the old glass window.

The cars were lined up on the grass next to Clarence's new barn (top of page 9) where members relaxed and swapped stories.

The next photo shows a beautiful Samarra Beige 37-46C Special Convertible Coupe belonging to **Karl and Dorothy Anderson** (#47). They have fun driving it everywhere including a trip south to Georgia, then to Oregon and return (9,700 miles or 15,500 km)!

In the bottom photo on page 9 we see master mechanic **Karl**

Anderson (with the hat) giving **Clarence Hoffman** (center) and **Steve King** some pointers on Clarence's new '37 46C Convertible brown Coupe.

After a tasty buffet lunch in the barn, some members took a much anticipated tour through Clarence's charming old farmhouse.

He has some beautiful antiques including a 1937 floor model radio. The top half opens to reveal a bar with drinking glasses in a fitted case with a shiny mirrored background. It's very beautiful and very rare.

A few of the tour group walked around the back of the house to the pond. In winter it freezes over you can go ice skating on it. The farm, barn and pond are all surrounded by green grassy fields with tall trees forming a pastoral background. What a beautiful, peaceful place!

My wife and I really enjoyed our visit and made many new friends. The tours were great and the Riverside Inn was unique. And Clarence did a great job organizing the meet and being our host. It's a trip we'll always remember!






Members and their Buicks lined up near Clarence's new barn.



Karl and Dorothy Anderson's '37 Special Convertible Coupe



Karl (with hat) looking at Clarence's new '37 Special Convertible Coupe




Clarence wearing his vintage army hat directs us to his farm.



The oldest part of his farmhouse dates from the 1860's.



The pond with the farmhouse and new barn in the distance.



BIG NEWS....OR HOW I DIED AND WENT TO HEAVEN

By Jim Terruso (#816)
West Bridgewater, Massachusetts

My 6 year wait is finally over! Now I have the car of my dreams. I found this black 1937 Century Sedan Model 61 through an ad in Old Cars Weekly. It was only 60 miles from my Massachusetts home.

The car was purchased at Hershey in 1988 by a fellow from New Hampshire. He kept it until 1992. The next owner repainted the car and had the chrome redone. He is a Ford collector and decided that the Buick didn't fit in with his plans. So "Thank you, I'll gladly take it."


The car has had a good sheltered life as the frame and undercarriage are clean and rust free. I found a small spot of rust in the trunk. The interior

and woodgraining needs to be redone. The engine and transmission are original. Would you believe, it still has the original 5 terminal voltage regulator!

I have tuned her up, replaced some of the wiring and installed a spark plug cover. For now I will work on some essentials and contemplate my winter projects.

Many thanks are due to my friend and fellow Club member **Charlie Ross** (#1015) from Warwick, R.I. who also owns a 37-61. Charlie helped me get this beauty home and supplied great moral support.

I can't begin to tell you the thrill it is finding and owning this car. Now I can really participate in our great Club.



My New Century

By Walter Fowler (#1195) - Green, New York

All my life I have been a Buick "NUT." The first Buick I remember was a '37 2-Door Special my dad bought new when I was 5 years old. He always had Buicks and I have had around 14 of them. At present I own four. Besides our daily driver, a '93 Roadmaster, I have a '65 Electra 225 convertible and a '71 Riviera. Both original and in top show condition.

My fourth Buick is this 1938 Century 4-Door Trunk Back Sedan which I purchased on May 31, 1996. The person I bought the car from had it for 7 or 8 years and obtained it from a man that had it in storage for about the same amount of time. Prior to that it had antique registration in Pennsylvania.


I attend between 15 and 20 shows per year. For the past 5 years, I have often seen and admired this '38 Century. It was always driven to the shows regardless of the weather or distance. The owner was never interested in selling until this year.


I have spent most of the time since I got

it just cleaning, adjusting, servicing and generally getting acquainted with the car. It has 101,000 miles on the speedometer. The interior is all original and in very good condition. All gauges work as does the factory radio with the dual speaker option. The tires are about 3 year old Lesters and the sidemount spares appear to be smooth originals that still hold air pressure.

The outside black lacquer finish appears to be a repaint some time ago. The bumpers and bumperettes have been rechromed. The radiator was recently recored and the engine is nicely detailed. The automatic choke has been replaced with a hand choke and push button starting. I still have the original choke minus the flexible shaft drive cable. Compression across the cylinders varies about 25 pounds, though it runs very nicely and cruises easily at 60 to 70 mph. The car has been at one show and took 1st place, so I guess it's in pretty good condition.


The car has the accessory front bumper grille guard but not a bumper medallion. The rear bumper has an aftermarket fold down guard. The





original owner's manual came with the car and I have purchased a repro Shop Manual. These together with the **Torque Tube** have helped me get acquainted with my Century.

I am a member of several other antique car clubs and enjoy their publications, but the **Torque Tube** seems so much more personal. Keep up the good work.






Technical TIPS

By Harry Logan (#651)

REAR BUMPER GRAVEL DEFLECTORS




The factory diagram above shows what the '37 & '38 Gravel deflector looks like and how it is mounted. All series Buicks had them when they left the factory, but few have them now. Chevrolet's had them also and you can buy reproduction ones. Hopefully you will soon be able to buy reproduction Buick gravel deflectors as well. (I'll keep you posted).

Notice the flat side is up and it mounts below the bumper brackets. I have seen several cars with them mounted on top of the bumper bracket with the curved side up. This is incorrect. The photo on the right shows the gravel deflector on *Andy Diem's* (#852) unrestored '37 Special Phaeton (this issue's cover car).

You can install the '38 rear folding accessory bumper guard and the deflector together. The lower nut that holds the folding guard comes close to the gravel deflector (see top of page 5).



'37/38 40/60 cars used the same deflector. '37/38 (as well as '39/'40) 80/90 series cars used the same type of deflector. All '37/38 gravel guards have a similar plain flat top and rounded bottom.

'39 and '40 40/60 series gravel deflectors were wider and had an embossed rib pattern instead of a flat plain top. They are noticeably different compared to the ones for our cars (see photo, page 15 top right).



There also were gravel deflectors under the running boards just in front of the rear fenders. Most are missing on the cars I've seen, but the holes to attach them are there. They could be easily made as they are just a piece of #16 gauge sheet metal bent at right angles. You could also easily make the special attaching bolts shown in the diagram by bending regular bolts.

(continued from page 14)




INTAKE MANIFOLD LEAK

By Harry Logan (#651) Los Altos, CA.

This photo shows a burn spot on the gasket because of a bad seal between the intake manifold and the head. This drastically changes the air/fuel mixture to two cylinders with a dramatic loss of power. Now you're basically running on only 6 cylinders. If it occurs on two ports as mine did, now you're only running on 4 cylinders. Your car will run very poorly indeed.

To test if you have a bad intake manifold seal, squirt some carburetor cleaner along the junction of the head and manifold and see if your motor speeds up. If it does, you've got a leak and a resultant power loss.

My intake manifold had been resurfaced (*ground flat*) to match the surface of the head for a better seal, but the pilot ring was not resurfaced. Because the pilot ring was now too wide, it prevented a tight seal, thus causing the leak.



Even though the manifold bolts were very tight, it still leaked. And you could not see it with your eye. It looked like a good, tight seal.

So the moral is, if you resurface the intake manifold, be sure to resurface the pilot rings to compensate for the difference in the depth you took off the manifold face.



Technical TIPS

BLEEDING THE BUICK BRAKE SYSTEM

(From the May, 1938 Motor Services Magazine)

Bleeding the brake system consists of the removal of air from the tubing and brake cylinders. Air in the system is usually caused by depressing the brake pedal when the fluid level in the master cylinder is too low, or by disconnecting some part of the hydraulic brake system.

This is a sectional view of a wheel brake cylinder (see Figure 1).

If the brake line from the master cylinder is disconnected, then it will be necessary to bleed all four wheel cylinders. If the line is disconnected at any wheel cylinder, only that cylinder need be bled.

BLEEDING ONE WHEEL CYLINDER

It is very important that the master cylinder reservoir be not less than half full during bleeding operations. Make sure it's full. The filler cap is accessible through the left front floor board. Next re-

move the bleeder screw shown at the upper right (see arrow in Figure 2). Sometimes you will not find it because it was never replaced the last time the brakes were bled. Attach a drain tube, allowing it to hang in a clean one quart (one liter) glass jar.




Figure 1

out of about one-half pint (one quarter liter) of liquid.

BLEEDING ALL FOUR WHEEL CYLINDERS

Again, make sure the master cylinder is full. Start at the left front first, then the right front, left rear and right rear, loosening one bleeder screw and valve at a time. When the liquid flows without air bubbles, close the valve.

Never attempt to bleed the system or depress the brake pedal while the brake drums




Figure 2

are removed. (ED. This will cause the wheel cylinder pistons to come out with the loss of brake fluid. We might add that it's a good idea to get a friend to help pump the brake pedal while you adjust the bleeder valve.)

ENGINE BLOCK CLEANING

By Gary Glazier (#1005) - La Crescenta, California

Engine overheating can be aggravated by dirt in the water jacket of the block. In my case ('38 Century), the caked mud was at least one inch deep at the rear (*low point*) of the engine. Presumably this represented 58 years of rust, flakes from deteriorating radiator hoses, gooey additives, etc. There were even pieces of wire, formerly coiled in the lower radiator hose.

I did this job with the engine in the car. It would be easier if the engine were out and mounted on a stand. Proceed as follows:

1. Drain coolant from radiator and block. The entire drain plug assembly should be removed from the block.
2. Remove head. Without access to the water passages in the top of the block, very little can be accomplished.
3. Cover valve lifter area on the right side of the engine to exclude dirt and water. This is very important.
4. Knock out freeze plugs on the left side of the engine. These should be replaced later with brass ones. Steel will rust out at some very inconvenient time.
5. If inspection shows you have mud build-up, gather up as much of the following as possible:
 - a. Several pieces of heavy wire, 3/32" (2.4 mm) and 1/8" (3.2 mm) by 18" (46 cm) long.
 - b. Long, thin screwdrivers
 - c. Hacksaw blades
 - d. Inspection light - the battery operated type, with a flexible probe and a tiny bulb at the tip.
 - e. Shop vacuum cleaner
6. Begin loosening the caked build-up nearest the freeze plug ports. Vacuum frequently. It is probably deeper than you think, so keep digging! At this point it is best to work dry (*no water*) to see what is happening.
7. As necessary, work down through the coolant ports on the top of the block with screw drivers and heavy wires. Wires should be

Technical TIPS



bent into curves and hooks as appropriate.

8. If compressed air is available, blow down through the top ports to get the dirt out to more accessible areas. Otherwise, use the wires to flick the chunks out into sight.
9. Don't give up....the job can be done. However, I spent at least two full days on this phase. The alternative was to have virtually no coolant flow around number 7 and 8 cylinders.
10. Once visual inspection shows most of the work is done, it is time to water flush. First, cover the generator and starter with plastic trash bags. Jack up the left front wheel so that the block drain can more efficiently get the mud out.
11. Using a garden hose, flush through the freeze plug ports. Ensure that the block drain hole remains clear of chunks. With the water running, work the heavy wires down through the top holes. Continue until drain water runs clear.

Was the effort worth it? Yes! Because with the build-up I had, none of the usual fixes (*new radiator, etc.*) would have completely solved an overheating problem. This was on an engine that externally was restored to look like new!

FURTHER NOTES:

No amount of normal radiator flushing would ever get this mess out. You have to see it to believe it.

After all this work, preserve the system by draining yearly, flushing and refilling with distilled water and name-brand antifreeze. Never put in additives because they will stay in there to be cleaned out in years to come.

Do put in a Gano radiator filter. (See the *Torque Tube*, July/August 1994). Any residual chunks floating in your block would love to clog the radiator!



Technical TIPS

MODIFYING YOUR TRUNK LOCK

By Wayne Yonce (#1034) - Fallbrook, California

Buick designed their trunk locks so they have to be locked. You cannot remove the key after you open the trunk.

You must close the trunk and rotate the key 180° which locks the trunk in order to remove the key.

This simple modification allows you to unlock and open the trunk and remove the key. Now your trunk can be opened and closed without using the key. Of course, the trunk is closed but not locked. Use the key if you want to lock the trunk.

This modification requires you to cut a slit identical to and 180° from the one shown in Part A. To do this:

Remove handle from trunk by removing the 1/2" nut inside the trunk.

Use a fine-pointed punch or small nail to



remove Pin D from the handle shaft near Point

B. Insert key in lock and remove lock cylinder A.

The hollow cylinder with the slit

may remain on the handle. It should come out

easily with a small screwdriver used to pry it out. Now cut a slit 5/32" wide by 1/2" long opposite the one already there. Be careful as it is soft metal and hollow. I mounted mine lengthwise in a vise with the factory slit facing up. Then I ran a 9/64" drill through this slit and drilled a hole in the opposite side. I did this several times until I had a rough slit. Next, I filed the rough slit so it matched the original one and reassembled the handle. Now I can open and close my trunk with or without a key. And I can still lock the trunk when ever I want to.




STRAIGHTENING WARPED PLASTIC RADIO GEARS

By Laurie Roberts (#1046) - Blockhouse Bay, Auckland, New Zealand

If your 1937 or 1938 Car Radio's dial does not turn, the problem is probably with these two plastic gears. These gears turn the dial when you rotate the tuning knob. The problem is either missing teeth or a warped gear. Warped gears were my problem. Here's how I straightened them.

I made two sets of blocks for each gear with recesses for the metal parts attached to the gears so they could be laid flat on the blocks. Then I heated the gears in hot water (not boiling water) for about 15 minutes. Next I clamped the gears in the blocks using a vise for a few hours.

After removing the straightened gears,




Technical
TIPS



I found that they would eventually return to their warped position. So I glued a thin metal washer to each gear, placed the gears back in the blocks, put some masking tape over the side of the gear with the washer to prevent any excess glue from sticking the blocks together and again put them in a vise until the glue dried.


Now the dial works perfectly. The only problem is the metal washers partially block the dial light. You could try repositioning the light or possibly using transparent plastic washers. This is only a problem when using the radio at night which I seldom do.






Technical TIPS

Dave Paulisin (#704) - Bloomfield, Michigan



This is what the Buick Sharkstooth Accessory Grille Guard looks like. It's shown on **Chris and Dorran Smith's** (#1216) '37 Century Slant Back Sedan Model 67. It's a little over 15" (38cm) long.




The back of the guard has 5 threaded holes which allows it to be mounted several ways. The center hole can be used if you have a hole through the bumper.

One member's bumper did not have a hole in the center. He did not want to drill a hole through the bumper, so he used a metal bar to mount the guard.




Some guards come with two mounting clips to clamp to the upper and lower edges of the front bumper. I have heard of a third way that uses two curved brackets that go on ei-

1937 SHARKSTOOOTH GRILLE GUARD




ther side of the bumper with a bolt through each end. The bolts go just above the edges of the bumper and screw into the guard.

So there seems to be several ways to mount the guard. My guess is that the clips were the standard way as they appear to be custom made to go with the guard. The upper clip is pointed while the lower one is more rectangular. They can get lost from the guard which is probably why some members have to end up making their own mounting bracket.



RUPTURED FUEL PUMP DIAPHRAGM

(ED: This article is based on a letter I received from a vendor of 6 volt electric fuel pumps)



If the diaphragm on your mechanical fuel pump ruptures and you switch on your electric fuel pump, it can pump gas into the crankcase. The vehicle will still run and you can not tell you have a ruptured diaphragm until you check the oil. Or it may pump gas onto the ground through the weep hole built into the mechanical pump's body. Or it may pump gas into the vacuum lines for the windshield wiper motor (on Big Series Cars). This gas usually goes into the intake manifold.

If this happens to you, the best thing to do is temporarily by-pass the mechanical fuel pump using a short section of rubber tubing. If you don't carry some in your trunk, remove the short section of hose that goes to the windshield wiper motor under the dash or on Specials, the wiper hose near the intake manifold.

As a general rule, the times you will want to use the electric pump is to prime the carburetor and to pump through the mechanical pump when you have vapor lock. That's why I would suggest using a toggle switch instead of push-button one.




Technical TIPS

Specials have the master cylinder mounted on the frame, so brake tubing can be connected directly to the master cylinder. But Big Series cars have the master cylinder mounted on the transmission, so it vibrates with the motor. That's why a flexible hose is used to connect the master cylinder to the junction box on the frame. This 9 1/2" (24 cm) hose is shown at the top of the photo.

This hose is becoming scarce. So someday you may have to use a substitute such as a coil of tubing instead of a hose. This is what is now used on some modern cars. This coiled tubing was on my '38 Century Coupe when I purchased it and apparently worked fine for the previous owners.

BIG SERIES MASTER CYLINDER HOSE

By Harry Logan (#651) Los Altos, CA.



NEW Members

Larry Bishop Jr. (#1206)
6829 Hoods Creek Road
Franksville, WI 53126
38-40?

Philip Harkins (#1207)
10890 4th St.
Hesperia, CA. 92345
37-64

Brad Odin (#1208)
2303 7th Street South
Moorhead, MN 56560
37-41
37-41
37-61

L. Mike Dougall (#1209)
P.O. Box 44
Thompson, CT. 06277
37-40C

David McIlvaine (#1210)
9003 Kane Rd.
Wadsworth, OH 44281
37-41
38-66S

Phil Mares (#1211)
9606 N>E> 4th St.
Midwest City, OK 73130

Larry Arrowood (#1212)
6300 Murray Lane
Brentwood, TN 37027
37-46C

Sigfred Haugen (#1213)
Granmovegen 15
N-3736 Skien,
Norway
38-46S
38-61

Nev Brooks (#1214)
P.O. Box 799
Bachhus Marsh 3340
Australia

Greg McKenzie (#1215)
4 Emlen Place
Mosgiel,
New Zealand
38-41

Christopher Smith (#1216)
4459 Snowden Ave.
Lakewood, CA. 90713
37-67

Neill McKinstry (#1217)
9565 St. Andrews
Perrysburg, OHIO 43551
37-47

Parts F O R S A L E

- **Parting 1937 & 1938 SPECIALS and a 1937 LIMITED.**

The following is just a portion of the parts available. Call with your needs.

- **1937 PARTS**

ROADMASTER dome light.....	\$ 20.
Bumper guards.....	\$ 20.
CENTURY front coupe seat, very good condition.....	\$ 200.
40/60 series floor pan.....	\$ 150.
40 series complete front end with rebuilt shocks.....	\$ 300.
Headlight adjusting buckets and reflectors.....	\$ 40.
NOS Special Flywheel and ring gear.....	\$125.
Trunk Handle, with key.....	\$25.
Gauge cluster with working temperature gauge.....	\$75.
SPECIAL Generator, 918G.....	\$75.
AA-2 complete, rebuildable.....	\$150.
CENTURY radiator.....	\$75.
Trunk back Sedan Trunk Lid.....	\$75.
Large Series Starter, working condition.....	\$ 75.
CENTURY motor and transmission, complete with original starter, fuel pump, carburetor, air cleaner and generator.....	\$1,500.
40/60 Series gas tank straps, 4 pieces.....	\$ 35.
Large series transmission.....	\$ 200.
SPECIAL starter, working.....	\$ 65.
Coupe trunk lid hinges.....	\$ 25. pr
Special radiator.....	\$ 75.
SPECIAL complete intake/exhaust manifold with heat riser, AA-1 carb, vacuum starter switch and linkage.....	\$250.
SPECIAL rims.....	\$ 25. each
Rear springs, 40/60. Good condition.....	\$100. pair
Radio delete plates.....	\$ 15.
Coupe garnish moldings,	call for prices
Hubcaps.....	\$ 10. each
Small & large series throttle linkage, complete.....	\$ 25.
Big Series Rocker assemblies, complete.....	\$ 50.
Fender lights.....	\$ 65. pair
Trunk lights with good lenses.....	\$ 50.
Tail lights with lenses, all series.....	\$ 50. pair
Wiper transmissions.....	\$ 50. pair
SPECIAL manifold.....	\$ 75.
Throttle cable.....	\$ 20.
SPECIAL transmission.....	\$ 75.
Rear view mirrors.....	\$ 15.
Steering column support with ignition, keyed.....	\$ 35.
Splash pans.....	\$ 35. pair

Rear motor mounts.....	\$ 15. pair
Headlight switches.....	\$ 20.
40 & 60 series doors.....	\$ 50. each
Radio grills.....	\$ 15.
Wiper motors.....	\$ 15.
Front vent window frames & mechanisms.....	\$ 25. each
Trunk hold up arms.....	\$ 20.
Sun visors.....	\$ 15. each
Steering sectors.....	\$ 50.
Bumper arms.....	\$ 15. each
Bumpers.....	\$ 30. each
Horn button.....	\$ 25.
Steering wheel.....	\$ 50.
Center stainless emblem.....	\$ 15.
40/60 running board brackets.....	\$ 50. set
37/38 Special exhaust valve body, working.....	\$ 50.
80/90 running board brackets.....	\$ 50. set
80/90 trunk support arm.....	\$ 20.

- **Parting 1937 Big Series Motor**, call with your needs
- **'37 LIMITED sidemount covers**, very nice. \$400.

• 1937-1938 PARTS

Map light switches, good used.....	\$ 15.
Small series spark plug covers, VG.....	\$ 50.
40/60 series front shocks, rebuilt.....	\$150. pair
Front license bracket, VG.....	\$50.
NOS Large series water pump.....	\$125.
NOS right front shock, 40/60.....	\$ 75.
NOS Voltage Regulator.....	\$ 75.
NOS large series thermostat housing with bypass.....	\$ 50.
SPECIAL Air Cleaner	\$50.
CENTURY Left Running board, solid and straight	\$125.
Sedan Rear Arm Rest.....	\$75. pair
Large Series transmission cluster gear, NOS	\$150.
Large Series transmission reverse idler gear, NOS	\$ 50.
Sidemount Covers, excellent condition	\$700. pair
CENTURY Sidemount covers, missing faceplates.....	\$200. pair
SPECIAL running board cores. Straight & rust free.....	\$200. pair
SPECIAL flywheel, excellent teeth.....	\$ 75.
Rear fender splash aprons.....	\$ 15. each
Big Series manifold ends.....	\$ 50. each

• 1938 PARTS

Defroster motor and dash vents.....	\$50. set
Trunk emblem.....	\$ 35.
Deck lid, no rust.....	\$ 75.
Breather tubes, Small (248) and Big (320) Series Engines.	\$ 10. ea

(Parts For Sale continued from page 24)

Trunk hold-up arms.....	\$ 20.
734Z starter with solenoid.....	\$ 50.
Horn buttons.....	\$ 10.
Radio hole plugs.....	\$ 15. set
SPECIAL hood lettering.....	\$20. pr
De-froster ducts.....	\$15. pr
Wiper transmissions.....	\$50. pr
'38 SPECIAL rims.....	\$ 35.
Rear license plate stand, bracket & light.....	\$ 35.
Bumper guards.....	\$ 25.
Tail lights, complete.....	\$ 75. pair
'38 assist straps with screws.....	\$ 15. each
Cowl stainless trim, very nice.....	\$ 20. pair
Throttle cable.....	\$ 20.
SPECIAL radiator.....	\$ 75.
Battery tray.....	\$ 20.
Generator.....	\$ 50.
Manifold.....	\$75.
Hood sides & tops.....	\$ 25. each
Gas Tank Door.....	\$ 10.
Sedan trunk weather strip, rubber, brand new.....	\$25.
Coupe trunk handle with base and license bracket.....	\$75.
Master heater with defroster and dash vents.....	\$100.
NOS 40/60 series tie rod ends.....	\$50.

All parts plus shipping

Dave Tacheny (#997)
11949 Oregon Ave. N.
Champlin, MN. 55316
(612) 427-3460

• 1937-1938 SPECIAL PARTS

2 Used Rear Brake Drums.....	\$30. each
Brake shoes for 4 wheels (8 shoes). Need relining. 1 3/4" wide.....	\$30.
Brake Backing Plate for right rear wheel.....	\$ 15.
NOS sleeve that holds the pinion gear bearing. Fits '36 to '55 SPECIALS. P/N 1336942.....	\$30.
NOS Transmission Reverse Idler gear. P/N 1283878.....	\$50.
NOS Delco-Remy Starter Armature P/N 823881.....	\$40.
NOS 4.44 Ring and Pinion Gear set in original carton.....	\$95.
Used Torque Ball with brass bushing.....	\$25.
'37 chrome radio grille with separate wire mesh screen. Needs rechroming.....	\$15.
Rechromed Left '37/38 Trunk Back Sedan Trunk hinge.....	\$50.
'38 Hood ornament, needs rechroming.....	\$15.
Engine Splash Pan, right side only.....	\$ 25.
• '37/38 Big Series thermostat housing with spring/brass washer & upper radiator hose gooseneck connection.....	\$35.
• '37/38 Big Series "X" fan, 18" diameter.....	\$25.

(Parts For Sale continued from page 25)

Pair of restored 1937 Minnesota license plates.....\$50.
Harry Logan (#651)
1005 Rilma Lane
Los Altos, CA. 94022
(415) 941-4587 PST

• **1937 PARTS**

Parking lights with pot metal.....	\$65.
Pot metal for parking light, very good condition.....	\$25.
Clock.....	\$25.
Gauges.....	?
Rear Leaf Springs, used but good - 40/60.....	\$85. set
4-Door sedan body stainless including cowl small stainless.....	\$?
Drivers side rear fenders - 40/60.....	\$40.
Generator, Big Series.....	\$50.
Engine, Big Series.....	\$350.

• **1937/1938 PARTS**

Map light switch, used.....	\$20.
Radio anti-static spring that goes on the front axle.....	\$20. set
NOS 4 post regulator.....	\$75.
Buick Hose clamp set.....	\$20. set
Rear window shade, used.....	\$40.
NOS Rocker arm shaft, with bushings, 40 series.....	\$110. set
New car cover, never used - 40/60 series.....	\$75.
Front wing vent - 40/60 series.....	\$45. set
Synchronizer gear, like new in box - Big Series.....	\$75.
Hydraulic lifters, cam, rocker assembly, push rods etc. - Big Series.....	\$225. set

• **1938 PARTS**

5 post regulator, used.....	\$30.
Transmission - 40 series.....	\$100.
NOS cluster gear - 40 series.....	\$85.
NOS Input or Pilot shaft - 40 series.....	\$35. each
16" wheels - 40 series.....	\$35. each
Engine - Big Series.....	\$350.

All prices plus shipping. Call between 9 AM and 1 PM EST Monday to Friday or anytime on Saturday and Sunday.

David Bylsma (#117)
7802 Chevalier Ct.
Severn, MD. 21144
(410) 551-7236

• 1938 SPECIAL

Transmission and rear end with 4.44 ring and pinion gears..... \$200.00
Engine splash pans, left and right \$ 40. pair

*Jim Carpenter (#1169)
2450 Dryden Ave.
Gilroy, CA. 95020
(408) 848-8935*

Parts WANTED

• For 1938 SPECIAL

- Right rear fender
- Fender Light Chrome Trim
- Fender light bullet glass. Will trade for '37 rounded type glass.

*Terry King (#826)
Los Angeles, CA
(213) 413-7901*

• For 1938

- Grille (no pitting, dents etc.)
- Dashboard

*Front Bumper Badge
Bill Whyte (#968)*

*Clerk's Acre
Lodgehill Road
Nairn,
IV12 4SZ
Highland Region,
Scotland
Tel: 01144 1667 452201
FAX: 01144 1667 456033*

• For 1937 CENTURY

- Steering wheel, horn ring and horn button
- Trunk handle with key
- Steering column ignition assembly with key

*Jim Terruso (#816)
(508) 587-6049 in Massachusetts*

• Fender skirts for my '38 SPECIAL Sedan

*James Rufener (#767)
1748 Karis Way
Eagan, MN 55122
(612) 688-8058*

• 1937 CENTER STAINLESS STRIP

*that runs between the Grille Halves.
Must be in excellent condition.*

*Joe Giordano (#333)
131 N. Stewart Rd.
Liberty, MO. 64068
(816) 781-5570*

• 1938 CENTURY and SPECIAL

SIDEMOUNT FENDERS and COVERS
*Walter Lalic (#999)
RD #2
New Brighton, PA. 15066
(412) 843-8206*

• My 1937 CENTURY needs:

- Water Pump
- 4 nice Hub Caps
- Bumper Badge
- Horseshoe Grille Guard.
*Steve Nathanson (#656)
69 Terrace Rd.
Walnut Creek, CA. 94596
(510) 947-6711*

EXTRA! EXTRA! BACK ISSUES NOW AVAILABLE

THE FOLLOWING BACK ISSUES ARE AVAILABLE FOR \$4.00 EACH POSTPAID.

- 1991-1992 VOLUME X - NUMBERS 1 THROUGH 9
- 1992-1993 VOLUME XI - NUMBERS 1, 2, 4, 5, 6 AND 7
- 1993-1994 VOLUME XII - NUMBERS 2, 4, 5 AND 6
- 1994-1995 VOLUME XIII - NUMBERS 1 THROUGH 6
- 1995-1996 VOLUME XIV - NUMBERS 2 THROUGH 6

----- Please make your checks payable to: -----

The 1937-1938 Buick Club 1005 Rilma Lane Los Altos, CA. 94022 USA

Cars WANTED

• **WANTED: 1937 Plain Back Model**

44, 47, 64 or 67.

Prefer low mileage, good condition driver (no heavy projects please). Authentic restorations OK. Realistically priced. 1938 plain back models OK. Send information, price and photos (will return) to:

Mike Dougall (#1209)
P.O. Box 44
Thompson, CT. 06277

• **WANTED: 1938 Convertible Coupe**

Special or Century

Plain fenders or sidemounts
In good running condition

*This ad is for Laurie Roberts (#1046)
in New Zealand.*

*Contact Harry Logan (#651)
1005 Rilma Lane
Los Altos, CA. 94022
(415) 941-4587*

Literature FOR SALE

1937-1938 Sales brochures, manuals, factory photos etc.

Send stamped envelope for free list.

Specify Buick and year.

Walter Miller (#1093)
6710 Brooklawn
Syracuse, NY 13211
(315) 432-8282

Cars F O R S A L E

- **1937 CENTURY** 4-Door Trunk Back Sedan

Rare original, runs excellent, new www, new gaskets, original interior, original spare, strong runner. Many NORS parts, rebuilt carb, manuals, car cover


\$8,037.00

Steve Nathanson (#656)

69 Terrace Rd.

Walnut Creek, CA. 94596

(510) 947-6711



- **1938 CENTURY** Trunk Back Sedan Model 61

Use for parts or restore. No engine, transmission or gas tank. I have a clear title. Price includes all Torque Tubes magazines from 1984 to date, Shop Manual, Fisher Body manual, Owners manual and two Master Parts Lists.

\$1,200.00

Best time to call is between 6 and 9 pm PST

William Rode (#144)

W. 21313 Sunwest

Espanola, WA. 99022

(509) 299-3274

- **1938 SPECIAL** 2-Door Slant Back Sedan

Complete and solid. Partially disassembled. Needs restoration.

\$3,500.00

Call Bob Hanson (608) 786-1785

- **1938 McLaughlin SPECIAL**

Model 44-19 Trunk Back Sedan

No. 1 condition. Rebuilt detailed engine. New woodgraining. Radio and Heater. Will drive anywhere. Showed at the 1995 Concours D'Elegance show at Amelia Island, FL. Beautiful Automobile!

\$15,000.00 or best offer

Bill Gillespie (#874)

6001-27 Argyle Forest Blvd, Suite 43

Jacksonville, FL 32244

(904) 779-2885

- **1938 Special 4-door convertible**

Located in Maryland. 60% restored, many new parts, excellent body with clear title. Delivery negotiable.

\$13,000. or best offer

David Bylsma

7802 Chevalier Ct., Severn, MD 21144

(410) 551-7236

- **1938 SPECIAL** Convertible Coupe 46C

Plain fenders. Car needs total restoration.

\$6,500.00

Doug Nelson (#51)

761 Hylo Rd. SE

Salem, OR 97306

(503) 399-0647

- **1938 SPECIAL** 2 Door Trunk Back Sedan

All original, never restored car. Original upholstery, running boards, glass etc. (some starting to fog a little). Heater, no radio or clock. Have complete history of car. Spent all of its life in Marion, Ohio until I brought it to California. Everything works (gauges, horn etc.). Good blackwall tires. Original cracked steering wheel. Whistler (dark) gray. Repainted once. Some rust in trunk and small spot on one fender. Plain fenders.

\$6,900.00 or best offer

Jodi Erickson

228 Sycamore

Rialto, CA. 92376

(909) 820-2762

REPRODUCTION *Parts* FOR SALE

1936-1940 Sidemount nuts, all series.....	\$ 1.00 ea
1937-1963 Muffler clamp, straight eight.....	\$ 5.00 ea
1937-1938 Horn ring, chrome plated brass.....	\$ 90.00 ea
1937-1938 Horn ring, unplated brass.....	\$ 65.00 ea
1937-1948 Firewall grommet (wiring harness) from engine to dash.....	\$ 5.00 ea
1937 Parking Light lens.....	\$ 30.00 pair
1938 Parking Light lens.....	\$ 30.00 pair
1934-1953 Series 40 Manifold gaskets.....	\$ 7.00 ea
1931-1953 Distributor Cap, 8 cylinder.....	\$ 8.00 ea
1931-1950 Distributor Rotor, 8 cylinder.....	\$ 4.00 ea
1937-1953 Point set, 8 cylinder.....	\$ 5.00 ea


Add 10% for shipping and handling. Minimum shipping charge \$3.00

Joe Krepps - 2486 Pacer Lane South, Cocoa, FL 32926-2606 • (407) 636-8777



J.B. Donaldson Co.

2533 W. Cypress St.
Phoenix, Arizona 85009
(602) 278-4505



Beautifully Recast
STEERING WHEELS

Thru 1953
\$2.00 for Brochure. Must Specify Year



WIRING HARNESES

AUTHENTIC REPRODUCTION
WIRING SYSTEMS THRU 1953
HAND CRAFTED WITH THE
FINEST MATERIALS
EACH SUPPLIED WITH:
LIMITED WARRANTY
INSTALLATION INSTRUCTIONS
SCHEMATICS

ALSO OFFERING:
WIRING SUPPLIES
CATALOG OR INFORMATION \$5



BOX 435 WAYNE, PA. 19087



Running Board / Rocker Moldings
1934 thru 1940 SSAE for Information
BUICK RESTORATION SERVICES
P.O. BOX 442, PERRY, MICHIGAN 48872


BOB'S

AUTOMOBILIA

(805) 434-2963

1937-38 BUICK

FRONT FLOORMAT
1937-38 All Models
Black or Brown
FF-378.....\$195.



DOOR WEATHERSEAL-SPONGE
Glue-in DW-378 \$1.70 ft.
Clip-in DW-80 \$3.40 ft.
Clips WC-80 \$.60 ea.



DOOR BOTTOM SEAL
Clip Type DW-369 \$1.85 ft



TRUNK SEAL-SEDANS. 1/2" Wide;
Ser. 80-90 TW-371 \$31.50
Sedans, 3/4" Wide;
Ser. 40-60 TW-371S \$31.50



TRUNK SEAL For COUPES. 5/8" X 1"
Sponge TL-369 \$2.00 ft.
1/2"X1"X16" TL-1129 \$47.50



CLUTCH and BRAKE PEDALS Series 40-60
Black CB-343BK \$5.50 ea.
Brown CB-343BN \$5.50 ea.



PEDAL FLOOR SEALS; All Models
..... FS-375 \$12.50 pr.



1937 ONLY! ACCELERATOR PEDALS Series
40-60 Back..AP-37BK \$28.00
Brown AP-37BN \$29.00



SHIFT BOOT. 1937-38 Series 40 Only!
Black \$9.75
Brown \$14.50



Series 80-90 Black

DOOR SILLS; Trim To Fit
2-Door \$62/pr. 2Door \$93/set.



GLOVE BOXES; \$27. ea.


PARKING LIGHT LENS..... \$17.50 ea



CARB. KITS:CARTER.....CK-360C \$26.00
STROMBERG..... CK-37XS \$26.00



TORQUE BALL SEAL KIT. All Models
TBK-343. \$26.00



VISOR "VANITY" MIRROR. VM-379 \$27. ea.



LICENSE PLATE FRAMES. Chromed Brass
LF-333P. \$60. Pair



FRONT END PARTS For 40-60 Series;
Upper Outer Kit \$39.00
King Pin Sets \$35.50
Lower Inner Bushings \$20.00
Tie Rod End \$27.00



EXHAUST MANIFOLDS

1937-38 Series 60-80-90
ENDS \$180. CENTER \$182. VALVE BODY \$195.



RUNNING BOARD INSULATORS. 1937-38



All Models. ALL NEW MATERIAL!
4 Needed Per Running Board.
RI-378S Set of 8 .. \$160.00



HOOD REST PADS. 1937-38 6-8 Per Car.
HR-378 3.50 ea.




DASH GLASS. SILK-SCREENED on
Back of GLASS in COLORS as
Original. 1937 SPEEDO DG-37 \$38.
..... RADIO....RG-37 \$23.
..... CLOCK.. CG-37 \$28.
1938..... SPEEDO DG-38 \$38.
..... RADIO....RG-38 \$23.
..... CLOCK.. CG-38 \$28.



PLASTIC DASH KNOBS DK-37(38) \$ 6.
PLASTIC DOOR HANDLE and Window
Winder RINGS .HE-37(38) \$ 6.



OUTSIDE DOOR HANDLE CHROME
and RUBBER GROMMETS.
1 FERRULE & 1 GROMMET Per Set.
1937 DGF-296 \$5./Set
1938..... DGF-380 \$5./Set



DOOR FERRULE INSTALATION TOOL.
\$20. Refundable if Returned Within
30 Days. DF-TOOL \$29.




1938 TRUNK HANDLE/LIGHT MOUNTING
SEAL DH-381 \$8.75



MOTOR MOUNT, FRONT. All Models
ROUND PADS..... SP-338 ... \$10. pr.
MOUNT MM-347 .. \$29. ea.



TRUNK HINGES for 40-60.Chrome Plated \$150. pr.



1937 HUB CAPS. All Ser..... HC-37 \$60. ea.
WHEEL Beauty Rings. 15' or 16' \$89./Set of 4
1937 or 38 HOOD ORNAMENT..... \$85.

SOME OTHER ITEMS WE STOCK; BEARINGS,
DECALS, ENGINE PAINT, DECALS, SHOP
MANUALS, PARTS BOOKS, BODY BOOKS and MORE.
SHIPPING:10%. max.\$9. min. \$4. Prepaid. C.O.D. Add \$5.


BOB'S AUTOMOBILIA BOX 2119 ATASCADERO CA. 93423 TELEPHONE (805) 434-2963
.VISA- MASTERCARD-DISCOVER or C.O.D. CATALOG #43 \$4.00 - PHONE ORDERS - (Write For Catalog)



Buick Upholstery and Top Kits

Since 1977

Hampton Coach has been producing the finest quality interior and top products available for GM cars. We offer complete interiors, seat upholstery, tops and related components. Call our Inquiry Department today, toll free at 1-888-388-8726 and we'll be happy to discuss your Buick's needs.




HAMPTON


Phone 508-388-8047 Fax 508-388-1113

P.O. Box 6, 6 Chestnut Street, Amesbury MA 01913

New for 1937-1938 BUICK



New stainless side mount emblems. Includes mounting screws on back side.
\$62.50 each



**New stainless convertible top latches & header hooks for
40 & 60 series Coupe & Phaeton
(6 piece set) \$365.00**



MAPLELEAF FABBRICATION & MACHINE

13912 SE 241st. Street, Kent, WA 98042
206-630-8887

© Torque Tube 1996-1997

